

1/2"气∏棘∏扳手

1551



配置文件

















- 每分□160□的空□□速
- 最大扭力81 Nm
- 最大气□: 6.2 Bar
- 空气消耗量113 升/分□
- 1/4"
- 最大螺栓尺寸M10

- 小型□□工具
- 高品[生]
- 易用气□开关
- 旋□方向的快速便捷□整
- 防止空气[]入工具的[][]


用途:

- 汽□行□
- 航空[]

- 重工[]
- 大型建筑机械
- 造船[]

重要事□!

■ 建□使用Unior气□套筒



		L	A	В	Nm	•
615319	1/2"	254	45	41	81	1370


^{*} Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

Photo (pictures)



Accessories











3/8"气□□□□□器和□滑器



1/2"气□□□□器和□滑器



□ 螺旋气□□管

Safety tips



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life
- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.



• Always disconnect tools not in use from the air supply.