

Гарнитура одвртувачи VDE ТВІ со тестер на волтажа

603CS6TVDETBI



Profiles



Product features

Гарнитурата вклучува:

- 4 х електричарски плоснат одвртувач VDETBI (article 603VDETBI) dim. 0.8x4.0x100, 1.0x5.5x125, 1.2x6.5x150
- 2 х одвртка крстач изолиран , VDE ТВІ изведба (613VDETBI) dim. PH 1x80, PH 2x100
- 1х тестер за напон 220-250V (article 630VDE) dim. 0.5х3.0х140

Product name	SKU	Article	Dimensions	Quantity
Гарнитура одвртувачи VDE TBI со тестер на волтажа	617043	603CS6TVDETBI	-	6
Одвртка изолирана плосната за Електричари , VDE TBI изведба	0	603VDETBI	0.8 x 4.0x100, 1.0 x 5.5x125, 1.2 x 6.5x150	3

Product name	S	KU	Article	Dimensions	Quantity
Одвртка крстач изолиран, VDE ⁻	i (PH)	0	613VDETBI	PH1x80, PH2x100	2
Тестер на напо			630VDE	0.5 x 3.0x140	1

^{*} Сликите на производите се симболични. Сите димензии се во мм, тежината е во грамови. Сите наведени димензии може да се разликуваат во ниво на толеранција

Usage (pictures)




Ергономската рачка е изработена за заштита на вашите дланки.







Голема контакт област на дланката=повеќе сила на момент на вртежи



Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.
- VDE tools that have several parts, have to be assembled correctly before use.
- When working with VDE tools avoid contact with water.

 Don't use tools that shows sign of wear and have the second layer of plastic visible.