



## "柏林"式]]皮剪

569R/7P



配置文件




- 材料:特种工具[]
- 落[],完全淬火与回火
- 刀刃感□淬火
- •
- 防腐[]保[]
- 浸塑料手柄

● 重开[]簧

用途:

● 以400N/mm<sup>2</sup>的力剪切最大厚度1.25mm[]]





\* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

## Safety tips

## $\checkmark$

• Be careful of sharp edges on the cutting edges of these tools.

• Use only hand pressure for cutting.

• Snips should be carefully put away after use. Wipe the cutting edges with a lightly oiled rag.

• Oil the pivot bolt on the snips occasionally.

## $\mathbf{X}$

- Don't try to cut sharp curves with straight cut snips.
- Don't resharpen a snip blade.
- Don't use snips as a hammer, screwdriver or pry bar. Use proper tools for the job.
- Don't store snips in a drawer with other tools. Tools with cutting edges should always be treated with extra respect.

• Never hammer, or use your foot to get extra pressure on the cutting edges.