



427/2FG



配置文件



- 材料:金属板材
- 000038-40HRC
- 极易□理


- 六角□接
- 通□旋□端口□□,□置□□的□□□径
- 有6、10、16、25、35、50mm²6个位置旋□凹槽
- 杠杆原理,用力小

	mm ²	
621555	6 - 50	1350

 $[\]ensuremath{^*}$ Images of products are symbolic. All dimensions are in mm, and weight in grams. All

listed dimensions may vary in tolerance.

用途 (pictures)



Frequently asked questions

Why is it necessary to use crimping pliers for cable connections? Why not simply use combination pliers?

When working with cable connections, you must use crimping pliers because this is the only way to press the connections together correctly and accurately. This is a requirement for the safety of the joints and provided for by the grooves/shapes on the pliers.