




- 4x imbusz behajtóhegy (6469C6,3): 3, 4, 5, 6
- 9x Torx behajtóhegy (6472C6,3): TX8, TX9, TX10, TX15, TX20, TX25, TX27, TX30, TX40
- 3x Pozidriv behajtóhegy (6466C6,3): PZ1, PZ2, PZ3
- 2x Phillips behajtóhegy (6463C6,3): PH1, PH2
- 2x lapos behajtóhegy (6460C6,3): 0.5x4.0, 1.2x6.5

Termék megnevezése	SKU	Cikk	Méreték	Mennyiség
Behajtóhegy-készlet, műanyag dobozban	621650	6776PB21	-	21
Lapos (SL) behajtóhegy, 3 darab		6460C6,3	0.5 x 4.0, 1.2 x 6.5	2
Pozidriv (PZ) behajtóhegy, 3 darab		6466C6,3	PZ 1, PZ 2, PZ 3	3
Torx (TX) behajtóhegy, 3 darab		6472C6,3	TX 8, TX 9, TX 10, TX 15, TX 20, TX 25, TX 27, TX 30, TX 40	9
Imbusz (HX) behajtóhegy, 3 darab		6469C6,3	3, 4, 5, 6	4
Phillips (PH) behajtóhegy, 3 darab		6463C6,3	PH 1, PH 2	2
Mágneses behajtóhegy-adapter, E6,3 (1/4")		6715E6,3	E6.3 (1/4")x75	1

* A termékképek illusztrációk. Minden feltüntetett méret milliméterben, a tömegek grammban. Az összes feltüntetett méret eltérhet a toleranciának megfelelően.

Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.