

# Izvijač imbus kuglasti TBI

#### 620TBI




#### Profili



### Atributi proizvoda

- vrh od krom-vanadij-molibdena, u cjelosti ojačan i zakaljen
- tijelo kromirano, vrh bruniran
- ručka ergonomski oblikovana
- trokomponentni materijal
- otvor u dršci za viješanje



|        | •   | С   | L   | D   | •   |
|--------|-----|-----|-----|-----|-----|
| 611715 | 2   | 65  | 150 | 3   | 31  |
| 611716 | 2.5 | 75  | 160 | 3   | 34  |
| 611717 | 3   | 75  | 160 | 3.5 | 37  |
| 611718 | 4   | 100 | 200 | 5   | 68  |
| 611719 | 5   | 100 | 210 | 6   | 93  |
| 611720 | 6   | 125 | 245 | 7   | 128 |

|        | • | C   | L   | D  | •   |
|--------|---|-----|-----|----|-----|
| 611721 | 8 | 150 | 270 | 10 | 203 |

<sup>\*</sup> Slike proizvoda su simbolične. Sve dimenzije su u mm, masa je u g.

#### Upotreba (pictures)



## Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

# Safety (pictures)







