

数据表 uniortools.com

欧[]工具[]

940E4




配置文件



- 材料:金属板材
- •
- lock with key included also foam keyring
- 四个[]子,其中一个[]子[]制[]
- 0000000
- 合成材料制成的□□有助于抽□和工具防□防震
- 7个抽[](五个尺寸[]560x365x70mm, [][][][]560x400x150mm)

- 手柄和□□的基本尺寸□L760×W440×H895mm
- 抽□□容量:140升
- 无□静□□荷:1600公斤
- ____:300__
- 每[]抽[]]荷能力:45公斤
- 抽□兼容SOS工具托□1/3,2/3,3/3
- 可添加挂件



	L	В	H	L1	H1	1	
608545	770	440	895	700	768	52000	

* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

Accessories



欧[]工具箱 - 3[]抽[]



欧||工具箱 - 5||抽||



940E和940EV小抽[]分隔套装



| |940E和940EV的4件分隔套装





940E和940EV文件架





Lock with keys



Ball-bearing slide, set of 1 pair



Safety tips



 Lock all your drawers before trying to roll the tool carriage into a new work area.

• Set the brakes on the locking casters after you have rolled the cabinet to your work area.

 Treat you tool carriage, tool chests, or tool boxes with respect.

Always follow the prescribed max load capacity of individual drawers and the carriage as a whole.

Always put heavier objects in the bottom drawers

Always close drawers when not in use.

Always follow manufacturer manual instructions regarding assembly and repair of your tools.

\mathbf{X}

 Don't open two or more drawers at the same time, there is high chance of it tipping over.

Don't throw tools into drawer, always put the tools in.

Don't use an opened drawer as a working surface.

 Don't clean a lacquered surface with a solvent cleaner.

Don't pull a tool carriage as you won't be able to see where you are headed. Push it in front of you so you can see where you are going.

Don't stack a tool carriage with too many extra chests or tool trays; it may tip over at the most unexpected time.

Don't roll a tool carriage with loose tools

or parts on top of the carriage.

• Don't roll a tool carriage too quickly; a pot hole in the floor or some hardware on the floor may cause an accident.

• Don't overload the drawers; if you haven't got room for all of your tools, you need a larger tool carriage.

• Don't open up too many loaded drawers at a time; close each drawer before opening up another. Heavily loaded opened drawers are an invitation to tipping.