

170/2




### 配置文件






- 材料：□□□
- 落□，完全淬火与回火



- 棘□：□个方向均可，可通□按□更□
- 72 - □□5°□□□□
- 扳手棘□部分上的止□□可防止扳手在螺母上意外滑落
- 可以方便快捷的□固螺母，且不会□用□造成□失，同□□可以□□使扳手快速准确定位。



		L	B2	B1	A2	A1	
622851	6 x 8	114,2	17,4	17,4	8,4	8,4	40
622852	8 x 9	130,4	20,9	17,4	8,4	8,4	55
622853	8 x 10	130,4	20,9	17,4	8,4	8,4	55

		L	B2	B1	A2	A1	
622854	10 x 11	144,4	22,9	20,9	9,7	8,4	72
622856	12 x 13	166	24,9	23,4	9,7	9,7	97
622857	14 x 15	181,4	30,4	27,4	11,7	10,1	142
622858	16 x 18	205,9	33,9	30,4	12	11,7	198
622859	17 x 19	224,4	34,4	31,9	12	11,7	211

\* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

## Frequently asked questions

### **Do wrenches with a ratchet need to be oiled?**

No, the ratchet mechanism should not be oiled, but the dirt should be removed with a non-corrosive cleaning agent.