

Brusilica pneumatska kutna

1516A



Profili



Atributi proizvoda


- 20.000 o/min u slobodnom hodu
- max. pritisak zraka: 6, 2 bara
- potrošnja zraka: 113 l/min
- priključak za zrak: 1/4"
- promjer čahure: 6 mm
- unutrašnji promjer cijevi: 10 mm

Prednosti:

- ova kutna brusilica omogućava pristup teško dostupnim mjestima
- sigurnosna ručica sprječava slučajno uključivanje alata
- jednostavno postavljanje malih reznih ploča (brusnih/polirnih čepova)
- izuzetna snaga
- Lagan i kompaktan alat
- stupanjaska regulacija brzine okretaja

Upotreba

- precizno brušenje
- potpuno brušenje
- industrija alata
- Automobilska industrija
- Avionska industrija
- čišćenje varova
- čišćenje betonskih površina i zidova
- čišćenje drvenih površina
- odstranjivanje boja i lakova
- odstranjivanje hrđe
- brušenje ležajeva
- brušenje ventila motora
- brušenje zupčanika i navoja
- razne druge pripreme površina



617732

L

162

A

76



740

* Slike proizvoda su simbolične. Sve dimenzije su u mm, masa je u g.

upotreba (pictures)



Photo (pictures)



Accessories



Spojnica muška



Spojnica muška



Spojnica ženska



Spojnica ženska



Pripremna grupa 3/8"



Pripremna grupa 1/2"



Cijev spiralna za zrak

Safety tips



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.



- Always disconnect tools not in use from the air supply.

- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.