

# Jeu de tournevis TBI en coffret plastique

607PB8TBI



## Profils







## Description produit

- Dimensions du coffret : 307 x 260 x 55

## Le jeu comprend :

- 1 tournevis plat TBI (réf 602TBI) dim 0.5x3.0x100
- 3 tournevis plats TBI (réf 605TBI) dim 0.8x4.0x100, 1.0x5.5x125, 1.2x6.5x150

- 2 tournevis PHILLIPS TBI (réf 615TBI) dim PH 1x80, PH 2x100
- 2 tournevis POZIDRIV manche TBI (réf 625TBI) dim PZ 1x80, PZ 2x100

Nom du produit	SKU	Article	Dimensions	Quantité
Jeu de tournevis TBI en coffret plastique	621445	607PB8TBI	-	8
Tournevis TBI électricien pour vis à fente		602TBI	0.5 x 3.0x100	1
Tournevis TBI mécanicien pour vis à fente		605TBI	0.8 x 4.0x100, 1.0 x 5.5x125, 1.2 x 6.5x150	3
Tournevis TBI pour vis à empreinte PHILLIPS		615TBI	PH 1x80, PH 2x100	2
Tournevis TBI pour vis à empreinte POZIDRIV		625TBI	PZ 1x80, PZ 2x100	2
Coffret plastique pour composition de douilles et accessoires		981PBS2	307x260x55	1

\* Les images des produits ne sont pas contractuelles. Toutes les dimensions sont en mm, les poids en grammes.

## Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

of steel into the operator's arm or even towards his eyes.

## Safety (pictures)

