

大力士工具□

940H1




配置文件



- 材料:金属板材
- 000(2000)
- lock with key included also foam keyring
- 四个[]子, 其中[]个[]子[]制[]
- 0000000
- 抽□开关□便,允□使用者同□拉开不同□格的抽□
- 合成材料制成的□□有助于抽□和工具防□防震
- 7个正面抽□, 尺寸560x365 mm (5个高度□70 mm, 2个高度□150 mm)
- 7个[]面抽[],尺寸390x323 mm (5个高度[]70 mm,2个高度[]150 mm)

- 手柄和□□的基本尺寸□1182×W640×H955mm
- 抽□□容量:215升
- 0000000
- 无□静□□荷:2300公斤
- 00000:55000
- 00000025 kg
- 正面抽□容量: 45 kg
- 抽□兼容SOS工具托□1/3,2/3,3/3

- 工具架穿孔背板允□用工具挂□挂起工具
- 作□一个配件,□可提供□□器支架,方便存□高□fi 68mm的□□器,以及一个□□的后□



	L	L1	L2	В	B1	Н	H1	•
615510	1182	1040	1080	640	550	955	800	115600

^{*} Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

用途 (pictures)



Accessories











■■■ 920PLUS、940E和940EV的空SOS工具托[]



配件







Safety tips



- Lock all your drawers before trying to roll the tool carriage into a new work area.
- Set the brakes on the locking casters after you have rolled the cabinet to your work area.
- Treat you tool carriage, tool chests, or tool boxes with respect.
- Always follow the prescribed max load capacity of individual drawers and the carriage as a whole.
- Always put heavier objects in the bottom drawers
- Always close drawers when not in use.



- Don't open two or more drawers at the same time, there is high chance of it tipping over
- Don't throw tools into drawer, always put the tools in.
- Don't use an opened drawer as a working surface.
- Don't clean a lacquered surface with a solvent cleaner.
- Don't pull a tool carriage as you won't be able to see where you are headed. Push it in front of you so you can see where you are going.
- Don't stack a tool carriage with too many extra chests or tool trays; it may tip over at

- Always follow manufacturer manual instructions regarding assembly and repair of your tools.
- the most unexpected time.
- Don't roll a tool carriage with loose tools or parts on top of the carriage.
- Don't roll a tool carriage too quickly; a pot hole in the floor or some hardware on the floor may cause an accident.
- Don't overload the drawers; if you haven't got room for all of your tools, you need a larger tool carriage.
- Don't open up too many loaded drawers at a time; close each drawer before opening up another. Heavily loaded opened drawers are an invitation to tipping.