

SET kaçavidash TBI me gjashtëkëndësh, në kuti kartoni

600CS5TBI




Profiles





Product features

Seti përfshin:

- 1x kaçavidë e rrafshhtë TBI (artikulli 605TBI) dim. 0.8x4.0x100
- Kaçavidë e rrafshhtë TBI me mbajtës gjashtëkëndësh 2x (artikulli 600TBI) dim. 1.0x5.5x100, 1.2x6.5x125
- Kaçavidë 2x me majë plus (PH) TBI me mbajtës gjashtëkëndësh (artikulli 616TBI) dim. PH 1x80, PH 2x100

| Product name | SKU | Article | Dimensions | Quantity |
|---|---|-----------|---------------|----------|
| SET kaçavidash TBI me gjashtëkëndësh, në kuti kartoni | 614007 | 600CS5TBI | - | 5 |
| Kaçavidë e rrafshhtë TBI |  | 605TBI | 0.8 x 4.0x100 | 1 |

| Product name | SKU | Article | Dimensions | Quantity |
|---|---|---------|------------------------------|----------|
| Kaçavida të rrafshta TBI me gjashtëkëndësh |  | 600TBI | 1.0 x 5.5x100, 1.2 x 6.5x125 | 2 |
| Kaçavidë kryq (PH) TBI me mbajtës gjashtëkëndor |  | 616TBI | PH 1x80, PH 2x100 | 2 |

* Imazhet e produkteve janë simbolike. Të gjitha dimensionet janë në mm, pesha në gram. Të gjitha dimensionet e listuara mund të ndryshojnë në tolerancë.

Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.

Safety (pictures)

