

Pneumatic haakse schuurmachine

1517S



Profielen



Product attributen

- free speed 4500 revolution per minutes
- maximum air pressure: 6,2 Bar
- air consumption 340 l/min
- air inlet 1/4"
- spindle thread 5/8"


Voordelen:



- small and compact tool
- suitable for lefthanders as well as for right-handers
- removable handle
- handy turn-on switch

Gebruik:

- grinding of welds
- grinding of sharp edges

- reparation of small uneven surfaces



	L	A	D	
617729	375	100	175	2610

* Afbeeldingen van producten zijn symbolisch. Alle afmetingen zijn in mm en gewicht in gram. Alle vermelde afmetingen kunnen variëren in tolerantie.

Gebruik (Afbeeldingen)



Foto (Afbeeldingen)



Accessoires

 Koppeling, man

 Koppeling, man

 Koppeling, vrouw

 Koppeling, vrouw



Pneumatische filterdrukregelaar en olieverniveelaar 3/8"



Pneumatische filterdrukregelaar en olieverniveelaar 1/2"



Spiraalslang

Veiligheidstips



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
 - Regularly clean and dry the air filters and inlet air supply.
 - Always use clean and dry air with the correct mixture of oil, for maximum tool life.
 - Check the joints and ensure that the tubes and other equipment are not damaged before use.
 - All tools should be gently oiled prior to being stored.
 - Always store pneumatic tools in dry places away from water.
 - Always use original spare parts.
 - Repairs can be performed only by authorised staff people authorised by Unior d.d.
- Always disconnect tools not in use from the air supply.