

# Biax pneumatic

1516



## Profile



## Caracteristicile produsului

- viteza de rotatie 25000 rotatii/minut
- Presiunea maxima de aer comprimat:6, 2 Bar
- consum de aer comprimat 113 l/min
- Racord de aer 1/4"
- capacitate de prindere mandrina 6 mm
- diametrul interior furtun 10mm


## Avantaje:

- levier de siguranta care previne pornirea accidentala
- prindere simpla a discurilor de slefuire si a celorlalte parti/extensii
- putere mare bazata pe marime
- scula mica si compacta
- reglare continua si variabila a rotatiei

## Utilizare

- polizare precisa

- polizare completa
- scula industriala
- industria auto
- industria aerospatiala
- curatarea sudurii
- curatarea betonului si a suprafetelor de pereti
- curatirea suprafetelor de lemn
- inlaturarea vopselelor si a lacurilor
- inlaturarea ruginii
- curatire rulmenti
- curatire valve motor
- curatire piniane si ambreiaje
- alte suprafete diverse



617731

L

155

A

60



390

\* Imaginea produsului este simbolica.Toate dimensiunile sunt exprimate în mm,greutatea în grame.

0 (pictures)



## Photo (pictures)



## Accessories



Cuplaj, partea tata



Cuplaj, partea tata



Cuplaj, partea mama



Cuplaj, partea mama



Filtru regulator si ungator pneumatic 3/8"



Filtru regulator si ungator pneumatic 1/2"



Furtun pneumatic elicoidal

## Safety tips



- The pressure in the tool during the operation has to be at least 6.2 bar for the tool to work properly.
- Regularly clean and dry the air filters and inlet air supply.
- Always use clean and dry air with the correct mixture of oil, for maximum tool life.



- Always disconnect tools not in use from the air supply.

- Check the joints and ensure that the tubes and other equipment are not damaged before use.
- All tools should be gently oiled prior to being stored.
- Always store pneumatic tools in dry places away from water.
- Always use original spare parts.
- Repairs can be performed only by authorised staff people authorised by Unior d.d.