

# Плоскогубцы комбинированные для электроники

406/4E




## Профили

---



## Описание товара

- материал: углеродистая сталь Premium Flex Plus
- кованые, целиком подвергнуты закалке и отпуску
- режущие кромки подвергнуты индукционной закалке
- износостойкие двухкомпонентные рукоятки



	L	B	C	A	
620069	120	13.6	15.8	8.2	90

режущая способность (10 Н = 1 кг)

	L	max 750 N/mm <sup>2</sup> Øf
620069	120	1,5

\* Изображения продуктов носят демонстрационный характер. Все размеры указаны в миллиметрах, вес в граммах.

## Использование (картинки)



## Фото (картинки)



## Советы по безопасности



- Pliers should be oiled regularly. A drop of oil at the hinge will lengthen the tool life and assure easy operation.
- When cutting wire with pliers, you should always wear glasses or goggles.
- Handles are provided for comfort. They are not intended to give user any degree of protection against electric shocks and should never be used on live electric circuits.



- Don't use pliers for cutting hardened wire, unless specifically manufactured for this purpose.
- Don't expose pliers to excessive heat. This may ruin the tool.
- Don't use pliers as a hammer.
- Don't hammer on the handles. They may crack or break.
- Don't extend the length of plier handles to secure greater leverage.
- Don't use pliers on nuts or bolts. A wrench will do a better job and with less risk of damage to the fastener.