

重型管扳手

492/6-H




配置文件



- 材料:特殊合金制成的把手, □久耐用
- ullet
- 可更□□□, 磷酸□□理
- 可□上□□
- 把手上漆

用途:

- 不可拆卸□接金属□
- 每个工具上都□有工具重量
- 工具上的[]足[]大,可以容[][]根[][]
- Unior用于高空作□的工具被□□成保留工具的基本功能、人体工程学和效用,或者尽可能□少它□的附加功能。



	L"	@	O_max	L	ů
626113	10"	1.1/2"	49	250	760

^{*} Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

Safety tips



- Always change tools in secure areas where there is no risk of falling tools.
- Always use tools with Unior carabiners and never use carabiners with a diameter less than 6mm.
- Tools being used at height should regularly be checked for damage and that there is no damage to lanyards, carabiners, attachment rings or belts.



- Don't use tools without attaching them to your work belt when working at height.
- Don't use and fix damaged tools.
- Don't exceed maximum weight of 2.3kg for individual tools that a worker can attach to their belt.

Frequently asked questions

Can we use a tool for working at height as a normal tool?

A tool for working at height has the same usability as a normal tool, except that a non-removable riveted metal buckle is added to this tool.

Does the stated weight per tool for safe work at height also include the weight of the metal ring?

The weight of the tool marked on the tool, included also weight of metal ring